

General Information

Registration No.	SR-2D-5811	Transmission	Automatic
Chassis No.	MHFAA8AF000084327	Model Year	2026
Engine No.	2NR-Y694089	Colour	White Pearl
Make	Toyota	Location	REP
Model	Yaris Cross	Fuel Type	Petrol
CC	undefined	Mileage	3,808
Grade	Great	Expiry Inspection License	
Type of Body	SUV	Expiry - Insurance	19-06-2030

Overall Evaluation

B+
Great

Interior

B+
Great

Frame

B+
Great

Exterior


B
Good

Functional

B+
Great



Damage Illustration - Interior



Damage Illustration - Exterior

Inspector Note

recondition 250\$

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Photo

Exterior Front



Exterior Front Left



Exterior Front Right



Engine



Registered Document



Interior Front Left



Interior Rear Left



Interior From Rear Seat To Front



Exterior Rear Left



Exterior Rear Right



Exterior Rear



Rear Back Door Room Trunk Hood



Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Tool Kits



Interior Rear Right



Interior Front Right



Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Interior

B+
Great



Illustration Damage

Damage Symbol:

a	Worn / Scrath / Cut / Crack / Peel / Fray
d	Worked / Loose / Deformed / Traces of Adhesive Tape / Grime / Repair Mark / Sunburn / Crinkle
k	Animal Hair
s	Smell
t	Cigarette Burns
x	Missing / Partially Missing
y	Grime

Damage level:

1	Minimal	3	Medium
2	Small	4	Large

Area	Parts Name	Damage Name	Damage Level
-	Overall Interior	-	-
1	Ceiling	-	-
	Switchs	-	-
	Room Mirror	-	-
	(L) Sunvisor	-	-
	(R) Sunvisor	-	-
	Sunglass Holder	-	-
	Front Room Lamp	-	-
	Rear Room Lamp	-	-
2	Dashboard	-	-
	Glove Box	-	-
	Instrument Panel	-	-
	Steering Wheel	-	-

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Area	Parts Name	Damage Name	Damage Level
3	Knobs	-	-
	Console	-	-
	Switchs	-	-
	Vents	-	-
	Display	-	-
	Audio System	-	-
4	Carpet	-	-
	(R) Front Floor Lag	-	-
	(L) Front Floor Lag	-	-
	Lag Other	-	-
5	(R) Front Seat	-	-
	(R) Front Seat Knobs	-	-
	(R) Front Seat belt	-	-
6	(R) Front Trim	-	-
	(R) Rear Trim	-	-
	Trim Other	-	-
	Switchs	-	-
7	Rear Seat	-	-
	Trim Other	-	-
	Seat belt Other	-	-
8	Trunk Room	-	-
9	(L) Front Seat	-	-
	(L) Front Seat Knobs	-	-
	(L) Front Seat belt	-	-
10	(L) Front Trim	-	-
	(L) Rear Trim	-	-
	Trim Other	-	-
	Switchs	-	-

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Coating Thickness

Bonnet	Left Front Fender	Left Front Door		Left Rear Door	Left Rear Fender	Roof	Trunk
✓ !	✓ !	✓ !		✓ !	✓ !	✓ !	✓ !
	Right Front Fender	Right Front Door		Right Rear Door	Right Rear Fender		
	✓ !	✓ !		✓ !	✓ !		

Panel Name	Panel Result	Panel Name	Panel Result
1. Bonnet - Left - Center - Right	Abnormal	7. Left Rear Fender - Left - Center - Right	Abnormal
2. Trunk - Left - Center - Right	Abnormal	8. Right Front Fender - Left - Center - Right	Abnormal
3. Roof - Left - Center - Right	Abnormal	9. Right Front Door - Left - Center - Right	Abnormal
4. Left Front Fender - Left - Center - Right	Abnormal	10. Right Rear Door - Left - Center - Right	Abnormal
5. Left Front Door - Left - Center - Right	Abnormal	11. Right Rear Fender - Left - Center - Right	Abnormal
6. Left Rear Door - Left - Center - Right	Abnormal		

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Frame

B+
Great

Parts Name	Damage Score
Front Cross Member Support	Normal
Right Front Inside Panel (Front Side)	Normal
Left Front Inside Panel (Front Side)	Normal
Right Front Inside (Rear Side)	Normal
Left Front Inside (Rear Side)	Normal
Left Front Pillar	Normal
Right Front Pillar	Normal
Right Center Pillar	Normal
Left Center Pillar	Normal
Center Floor Panel	Normal
Under Spare Box	Normal
Rear Side Member & Trunk Room Floor	Normal
Left Tyre House	Normal
Right Tyre House	Normal
Front Floor and Side Member	Normal
Front Floor Panel and Front Frame	Normal
Rear Frame	Normal

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Exterior

B
Good




Illustration Damage

Damage Symbol:

A	Scratch / Peeled / Crack / Cut
B	Modified
C	Corrosion
G	Stone Chip
P	Faded (Color,Gross)
S	Rust
U	Dent / Bent
X	Stuck
Y	Crack / Gap / Cap / Damaged

Damage level:

1	Minimal	3	Medium
2	Small	4	Large

Area	Parts Name	Damage Name	Damage Level
0	Overall Exterior	-	-
1	Supplemental Mirror	-	-
	(R) Front Tyre	-	-
	(R) Front Fender	-	-
	Molding	-	-
	(R) Front Wheel	-	-
	Wheel Cover	-	-
2	(R) Side Window	-	-
	(R) Mirror	-	-
	(R) Front Door	-	-
	Molding	-	-
4	(R) Rear Door	-	-

Inspection Date		September, 01 2026	Vehicle Type		Toyota SUV undefined 2026
Location		REP	Registration no		SR-2D-5811
Area	Parts Name	Damage Name		Damage Level	
4	Molding	-		-	
5	(R) Rear Tyre	-		-	
	(R) Rear Corner Panel	-		-	
	(R) Rear Fender	-		-	
	Molding	-		-	
	(R) Rear Wheel	-		-	
	Wheel Cover	-		-	
6	(R) Center Panel	-		-	
	(R) Step	-		-	
	In-panel	-		-	
	Side Spoiler	-		-	
7	(L) Front Tyre	-		-	
	(L) Front Fender	-		-	
	Molding	-		-	
	(L) Front Wheel	-		-	
	Wheel Cover	-		-	
8	(L) Side Window	-		-	
	(L) Mirror	-		-	
	(L) Front Door	-		-	
	Molding	-		-	
10	(L) Rear Door	-		-	
	Molding	-		-	
11	(L) Rear Tyre	-		-	
	(L) Rear Corner Panel	-		-	
	(L) Rear Fender	-		-	
	Molding	-		-	
	(L) Rear Wheel	-		-	
	Wheel Cover	-		-	
12	(L) Center Panel	-		-	

Inspection Date		September, 01 2026	Vehicle Type		Toyota SUV undefined 2026
Location		REP	Registration no		SR-2D-5811
Area	Parts Name	Damage Name		Damage Level	
12	(L) Step	-		-	
	In-panel	-		-	
	Side Spoiler	-		-	
13	Front Panel	-		-	
	Member (Bolted)	-		-	
	Front Bumper	Scratch		Medium	
	Grille	-		-	
	Lamps	-		-	
14	Bonnet	-		-	
	Headlight	-		-	
15	Roof	Repair Traces		Yes	
	Front Windshield	-		-	
	Rear Windshield	-		-	
	Roof Spoiler	-		-	
	Molding	-		-	
16	Trunk Hood, Rear Gate	Repair Traces		Yes	
	Antennae	-		-	
17	Rear End Panel	-		-	
	Muffler and Undercarriage Parts	-		-	
	Rear Bumper	-		-	
	Lamps	-		-	
	Panels	-		-	

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Functional

B+
Great

Parts Name	Damage Level Name
Retractable Mirror	Okay
All Warning Lamps Illuminate	Okay
Panel	Okay
Meter	Okay
Power Window (each)	Okay
Door Lock	Okay
Sun Roof	Okay
Power Seat	Okay
Power Steering Turning	Okay
Air Conditioner	Okay
12V Battery Condition	Okay
Smart Entry System	Okay
Remote Boot Release	Okay
Push-button Start	Okay
Audio, Radio	Okay
Reverse Camera	Okay
Parking Brake	Okay
Brake Pedal	Okay
Turn Signal	Okay
Hazard Flasher	Okay
Wipers	Okay
Washers	Okay
Horn	Okay
Seat Belts	Okay

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Parts Name	Damage Level Name
------------	-------------------

Spare Keys & Remote Controls	Okay
Parking sensor rear	Okay
Vehicle Jack and Tool Kit	Okay
Spare Tyre	Okay
Tyre Repair Kit	Okay

Mechanical

Parts Name	Damage Level Name
------------	-------------------

Engine coolant level	Okay
Radiator Fan	Okay
Radiator Core & Tanks	Okay
Coolant lines	Okay
Radiator Water Pump	Okay
Air Filter	Okay
Drive Belts	Okay
Oil Leaks	Okay
Engine Mounts	Okay
Engine Oil level	Okay
Clutch Fluid level	Okay
Brake Fluid level	Okay
Power Steering Pump	Okay
Power Steering Fluid level	Okay
Engine Starts Properly	Okay
Engine Accelerates Smoothly	Okay
Gear Changing is Smooth	Okay

Inspection Date	September, 01 2026	Vehicle Type	Toyota SUV undefined 2026
Location	REP	Registration no	SR-2D-5811

Disclaimer

This Grading Report is intended to record the general condition of the vehicle within the range of the set scope. This is not a comprehensive inspection guarantee. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

